



**Request for Proposal
For
Demolition and Removal of Manufactured Homes
And Property Clean-up
Otsego County, Michigan**

BID 2013-04

Proposals for demolishing/removing three manufactured homes and removing all junk/debris on the associated properties will be received by Otsego County, Michigan to the attention of John Burt in the Administration Office, 225 West Main Street, Suite 203, Gaylord, Michigan, 49735 by **Noon on Friday, August 9, 2013**. Bids will be publicly opened and read at 1:00 p.m. on **Friday, August 9, 2013** in Room 100 at 225 W. Main Street, Gaylord, MI.

Any questions must be received by Friday, August 2, 2013 at noon.

The County reserves the right to accept, reject or negotiate any or all bids, to waive or not waive informalities or irregularities in bids or bidding procedures, to rebid the project/purchase, and to accept any bid determined by the County to be in the best interest of the County, regardless of price. The reason for rejection may include past performance issues, and compatibility with existing equipment or software. Vendors located in Otsego County are hereby granted a 5% cost variance for low bid determination.

OTSEGO COUNTY

John M. Burt
Otsego County Administrator

SECTION II. INSTRUCTIONS, INFORMATION AND REQUIREMENTS

1. **Purpose:** The purpose of this Request for Proposal (RFP) is to receive proposals for selection of a contractor to provide proposals/bids for removing three county-owned manufactured homes along with removing all junk/debris on the associated properties. The three sites included in this proposal are 6036 Timberland Trail, 529 Arbutus Court, and 5730 Old Stump Road (See Attachment A for Location Maps).

This RFP does not constitute a contract for services performed or to be performed. After selection of the successful firm (referred to as the contractor), Otsego County, and the contractor will negotiate a contract and a complete scope of services.

All proposals submitted become the property of Otsego County and will not be returned. The County is not responsible for any costs incurred by the respondent in proposal preparation, presentations, site visits, or benchmarks performed.

2. **Submittal of Proposals/Bids:** Submittal of proposals/bids shall be on the form attached hereto in **Section V** no later than noon on Friday, **August 9, 2013**. Proposals shall be sealed and clearly marked as BID 2013-04 on the outside, and sent to the following:

John Burt, Otsego County Administrator
225 W. Main Street, Suite 203
Gaylord, Michigan 49735

Bids will be publicly opened and read at 1:00 p.m. on Friday, August 9, 2013 in Room 100 at 225 W. Main Street, Gaylord, MI.

3. **Official Signature:** An authorized official/person acknowledging full understanding of the information contained in this RFP must sign the Bid/Proposal Form.
4. **Inquiries:** Questions regarding the RFP should be directed to John Burt by calling 989-731-7527 or emailing to jburt@otsegocountymi.gov.

Any questions must be received by Friday, August 2, 2013 at noon.

5. **Insurance Requirements:** Contractor shall furnish a Certificate of Insurance from an insurance company licensed to do business in the State of Michigan and acceptable to the County for the following:

Commercial General Liability Insurance in the amount of \$1,000,000.

Worker's Disability Compensation Insurance including employer's liability coverage, in accordance with applicable statutes of the State of Michigan.

Motor Vehicle Liability Insurance, including Michigan no-fault coverage.

Any other Insurance that may be needed by the Contractor in order to fulfill contractual obligations.

Copies of subcontractor worker's disability compensation insurance will be required prior to commencement of work.

6. **Licenses:** The winning bidder hold any licenses necessary to work in the State of Michigan.

7. **References:** Bidder shall provide the names of three (3) commercial accounts for similar work performed. References are also required for any subcontractors.

8. **Evaluation and Award:** Bids/proposals shall be evaluated and awarded by the County as soon as practicable. Award of the bid will be based on quality, service, completion date, experience and price. Information on each of these categories shall be included in bid responses.

9. **Compliance with the Law:** Contractor shall comply with all applicable federal, State and local laws and ordinances, rules and regulations, as well as any applicable County policies.

10. **Timeline:** Please include a project timeline with your bid response.

SECTION III. SCOPE OF SERVICE

Furnish and provide all materials, supplies, tools, equipment, labor, supervision, and expertise to properly and professionally perform all required services described in this RFP.

The Contractor Responsibilities below pertain to three sites including 6036 Timberland Trail, 529 Arbutus Court, and 5730 Old Stump Road (See Attachment A for Location Maps). You can see photos of the properties in Attachment B.

CONTRACTOR RESPONSIBILITIES

- 1) Demolition/removal of mobile home.
- 2) Removal of all furniture, camper/trailers, and any other trash/debris found on the properties.
- 3) Cut and cap any lines linked to the mobile homes. The sites are on well and septic.
- 4) Contractor must obtain any necessary permits including filing of the Notice of Intent to Renovate.

Note: An Asbestos Study was conducted on each of the buildings with no asbestos being found (see Attachment C for Asbestos Survey Reports).

COUNTY RESPONSIBILITIES

- 1) Provide access to the facility and work areas as necessary for the project; and coordinate with County security services.
- 2) Provide prompt payment upon receipt of invoices and acceptance of the project work.

SECTION V. BID/PROPOSAL FORM

BID 2013-04

The undersigned proposes to furnish Building Demolition Services for Otsego County in accordance with the attached specifications stated herein for the price listed below.

TOTAL PROJECT COST \$ _____

Project Breakdown:

529 Arbutus Court \$ _____

5730 Old Stump Road \$ _____

6036 Timberline Trail \$ _____

Visited site to view project _____ yes _____ no

Submitted proposed schedule with bid _____ yes _____ no

Submitted references with bid _____ yes _____ no

COMPANY NAME: _____

ADDRESS: _____

SIGNATURE: _____

TITLE: _____

TELEPHONE: _____

EMAIL (if any): _____

FAX: _____


DATE: _____

ATTACHMENT A



Project Locations





Project Locations

Scale: 1" = 200'

Date of Photography: Spring, 2010





Project Locations

Scale: 1" = 100'

Date of Photography: Spring, 2010






Project Locations

Scale: 1" = 300'

Date of Photography: Spring, 2010





Project Locations

Scale: 1" = 100'

Date of Photography: Spring, 2010




ATTACHMENT B





529 Arbutus Ct.






5730 Old Stump Rd.







ATTACHMENT C

Rightway Remediation LLC
855 Doro Lane Saginaw, MI 48604 989.600.0055 phone 989.401.5353 fax

Otsego County
Attention Mr. Burt
225 W Main St #203
Gaylord, MI 49735
July 19th, 2013

Subject: 529 Arbutus Gaylord, MI 49735

Mr. Burt,

You retained us to perform an Asbestos Survey at 529 Arbutus Gaylord, MI 49735. The purpose of this survey is to identify building material that contain asbestos and as such will require special handling procedures and or removal activity before any general demolition may take place. This survey was conducted by Scott Krugielka A27600 on July 13th, 2013.

Site

This is a 700 square foot mobile home, built prior to 1980. The heating system was forced air, it the pipes are bare. There is fiberglass insulation with aluminum siding over a wood framed structure. Rightway uses trained and licensed inspectors to attempt to locate and identify building materials that contain asbestos. It should be noted that there is the possibility that some potential asbestos containing materials (ACM) that were not found. This would be due to the fact they were inaccessible to our inspector due to an area or section being unsafe to enter. They might not have been visible or for various reasons not sampled.

Scope of Work

The scope of this work is to conform to the AHERA, ASHRA and NESHAP acts. These acts are designed to protect the environment, the worker and the public. They are mandated standards which must be complied with before, during and after abatement activities.

Sampled Material Inventory

On July 13th 2013 our inspector took 2 samples for laboratory analysis of the following items, items in bold tested positive for Asbestos.

01 Linoleum Kitchen	02 Ceiling Tile Throughout
---------------------------	----------------------------------

Laboratory Analysis Procedures

The collected samples were submitted to EHS Laboratories, Environmental Hazards Service LLC in Richmond, Virginia. EHS Laboratories, Environmental Hazards Service LLC is an accredited lab; they are accredited by the American Hygiene Association and are participants in the National Voluntary Accreditation Program. As is protocol, Rightway followed chain of custody procedures to ensure proper handling and delivery of the samples to Apex Research. After Arrival at EHS Laboratories, Environmental Hazards Service LLC the samples were analyzed using Polarized Light Microscopy with dispersion staining in accordance to the United States Environmental Protection Agency guidance document EPA/600/R-93/116 dated July 1993 "Determination of Asbestos in Bulk Building Materials."

United States Environmental Protection Agency and The National Emission Standards for Hazardous Air Pollutants defines ACM as those materials that contain greater than 1% of asbestos. Asbestos is broken down into two categories, Friable and Non-Friable. By definition Friable ACM can be defined as those that can be crumbled or reduced to powder by hand pressure.

The Occupation Safety and Health Administration standard defines both Asbestos and Asbestos containing materials. The Occupation Safety and Health Administration define ACM as any material containing more than 1% of asbestos. In areas where when ACM or Asbestos work operations do not meet the 1% standard, while considered "unclassified" are still subject to engineer and work control practices. To determine the type of fibrous components and percentage, samples are visual inspected and the ration is determined by amount of fibrous material versus the total amount of material present.

Sampling Results and Recommendations

As previously indicated none of the items tested positive for asbestos or are assumed to be asbestos containing.

Prepared by:




Scott Krugielka
Asbestos Contract Supervisor/Asbestos Inspector
Accreditation Number: A27600
989.600.0055

Attachments:

- A: Scott Krugielka Asbestos Contractor/Supervisor license and Asbestos Inspector license
- B: Chain of Custody and Laboratory Results

Attachment A:
Scott Krugielka
Asbestos Contract Supervisor/Asbestos Inspector
Accreditation Number: 27600



Attachment B: Chain of Custody and lab results



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-07-02151

Client: Rightway Remediation Services
855 Doro Ln.
Saginaw, MI 48604

Received Date: 07/16/2013
Analyzed Date: 07/16/2013
Reported Date: 07/16/2013

Project/Test Address: 529 Arbutus; Gaylord, MI

Client Number:
23-6364

Fax Number:
989-753-4158

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-07-02151-001	A-1		Brown Fibrous; Beige Vinyl-Like; Inhomogeneous	NAD	35% Cellulose 5% Synthetic 60% Non-Fibrous
13-07-02151-002	A-2		Brown Fibrous; White Paint-Like; Inhomogeneous	NAD	90% Cellulose 10% Non-Fibrous

Rightway Remediation LLC
 855 Doro Lane Saginaw, MI 48604 989.600.0055 phone 989.401.5353 fax

Environmental Hazards Services, L.L.C

Client Number: 23-6364
 Project/Test Address: 529 Arbutus; Gaylord, MI

Report Number: 13-07-02151

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
-------------------	----------------------	------------	-----------------------	----------	-----------------

QC Sample: 65-M12003-3
 QC Blank: SRM 1866 Fiberglass
 Reporting Limit: 1% Asbestos
 Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020
 Analyst: Timothy Harris

Reviewed By Authorized Signatory: 
 Howard Vamer
 General Manager

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND:	NAD = no asbestos detected
---------	----------------------------



2 PM

Asbestos Chain-of-Custody

Environmental Hazards Services, LLC
 www.leadlab.com 7469 Whitepine Rd
 (800) 347-4010 Richmond, VA
 (804) 278-4907 (fax) 23237

Company Name: Rightway Remediation Address: 855 Doro Lane City/State/Zip: Saginaw MI 48604
 Phone: 989 600 0055 Fax: 989 401 5353 E-mail: office.rigt@gmail.com Acct Number:
 Project Name / Testing Address: 529 Arborus City/State (Required): Coaldale MI
 Allocated by: _____ Purchase Order Number: _____

Turn Around Times: 1-Day 2-Day 3-Day Same Day (Must Call Ahead) Weekend (Must Call Ahead)
 If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.

No.	Client Sample ID	Date Collected	ASBESTOS						AIR		Volume (Total Liters)	COMMENTS		
			FLM	FLM Point Count 400	FLM Point Count 1000	FLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEMAHERA (Air)	Time On			Time Off	Flow Rate (L/min)
1	A-1													
2	A-2													Living kitchen ceiling tile -
3														
4														
5														
6														
7														
8														
9														
10														

Released by: Scott E. Laursen Signature: _____ Date/Time: 7/15/13
 Received by: M. Blessing Signature: _____ Date/Time: 7/16/13

13-07-02151

 Due Date: 07/17/2013 (Wednesday)
 AE T

Rightway Remediation LLC
855 Doro Lane Saginaw, MI 48604 989.600.0055 phone 989.401.5353 fax

Otsego County
Attention Mr. Burt
225 W Main St #203
Gaylord, MI 49735
July 19th, 2013

Subject: 6036 Timberline Gaylord, MI 49735

Mr. Burt,

You retained us to perform an Asbestos Survey at 6036 Timberline Gaylord, MI 49735. The purpose of this survey is to identify building material that contain asbestos and as such will require special handling procedures and or removal activity before any general demolition may take place. This survey was conducted by Scott Krugielka A27600 on July 13th, 2013.

Site

This is a 600 square foot mobile home, built prior to 1980. The heating system was forced air, it the pipes are bare. There is fiberglass insulation with aluminum siding over a wood framed structure. Rightway uses trained and licensed inspectors to attempt to locate and identify building materials that contain asbestos. It should be noted that there is the possibility that some potential asbestos containing materials (ACM) that were not found. This would be due to the fact they were inaccessible to our inspector due to an area or section being unsafe to enter. They might not have been visible or for various reasons not sampled.

Scope of Work

The scope of this work is to conform to the AHERA, ASHRA and NESHAP acts. These acts are designed to protect the environment, the worker and the public. They are mandated standards which must be complied with before, during and after abatement activities.

Sampled Material Inventory

On July 13th 2013 our inspector took 3 samples for laboratory analysis of the following items, items in bold tested positive for Asbestos.

01 Linoleum Kitchen Dining Rooms	02 Linoleum Living, hallway, bedroom, utility rooms	03 Linoleum Bathroom
--	---	----------------------------

Laboratory Analysis Procedures

The collected samples were submitted to EHS Laboratories, Environmental Hazards Service LLC in Richmond, Virginia. EHS Laboratories, Environmental Hazards Service LLC is an accredited lab; they are accredited by the American Hygiene Association and are participants in the National Voluntary Accreditation Program. As is protocol, Rightway followed chain of custody procedures to ensure proper handling and delivery of the samples to Apex Research. After Arrival at EHS Laboratories, Environmental Hazards Service LLC the samples were analyzed using Polarized Light Microscopy with dispersion staining in accordance to the United States Environmental Protection Agency guidance document EPA/600/R-93/116 dated July 1993 "Determination of Asbestos in Bulk Building Materials."

United States Environmental Protection Agency and The National Emission Standards for Hazardous Air Pollutants defines ACM as those materials that contain greater than 1% of asbestos. Asbestos is broken down into two categories, Friable and Non-Friable. By definition Friable ACM can be defined as those that can be crumbled or reduced to powder by hand pressure.

The Occupation Safety and Health Administration standard defines both Asbestos and Asbestos containing materials. The Occupation Safety and Health Administration define ACM as any material containing more than 1% of asbestos. In areas where when ACM or Asbestos work operations do not meet the 1% standard, while considered "unclassified" are still subject to engineer and work control practices. To determine the type of fibrous components and percentage, samples are visual inspected and the ratio is determined by amount of fibrous material versus the total amount of material present.

Sampling Results and Recommendations

As previously indicated none of the items tested positive for asbestos or are assumed to be asbestos containing.

Prepared by:





Scott Krugielka
Asbestos Contract Supervisor/Asbestos Inspector
Accreditation Number: A27600
989.600.0055

Attachments:

- A: Scott Krugielka Asbestos Contractor/Supervisor license and Asbestos Inspector license
- B: Chain of Custody and Laboratory Results

Attachment A:
Scott Krugielka
Asbestos Contract Supervisor/Asbestos Inspector
Accreditation Number: 27600



Attachment B: Chain of Custody and lab results



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

**Asbestos Bulk
 Analysis Report**

Report Number: 13-07-02156

Client: Rightway Remediation Services
 855 Doro Ln.
 Saginaw, MI 48604

Received Date: 07/16/2013
Analyzed Date: 07/16/2013
Reported Date: 07/17/2013

Project/Test Address: 6036 Timberlane; Gaylord, MI

Client Number:
 23-6364

Fax Number:
 989-753-4158

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-07-02156-001A	B1	Flooring	Pale Tan/Pale Gray Pliable; White Granular; Inhomogeneous	NAD	1% Cellulose 99% Non-Fibrous
13-07-02156-001B	B1	Mastic	Translucent to Pale Yellow Adhesive; Homogeneous	NAD	5% Cellulose 2% Fibrous Glass 1% Synthetic 2% Hair 90% Non-Fibrous
13-07-02156-002A	B2	Flooring	Tan Vinyl-Like; Black Fibrous; Maroon Brittle; Inhomogeneous	NAD	45% Cellulose 10% Fibrous Glass 45% Non-Fibrous
13-07-02156-002B	B2	Mastic	Yellow Adhesive; Homogeneous	NAD	5% Cellulose 2% Fibrous Glass 1% Hair 92% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 23-6364

Report Number: 13-07-02151

Project/Test Address: 529 Arbutus; Gaylord, MI

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
-------------------	----------------------	------------	-----------------------	----------	-----------------

QC Sample: 65-M12003-3

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Timothy Harris

Reviewed By Authorized Signatory:



Howard Vamer
General Manager

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected



Environmental Hazards Services, LLC

www.landlab.com 7469 Whiteshoe Rd
 800)347-4010 Richmond, VA
 (804)276-4507 (fax) 23237

3 PM

Asbestos Chain-of-Custody



13-07-02156

Due Date:
 07/17/2013
 (Wednesday)
 AE

MSL

Company Name: Rightway Remediation LLC Address: 855 Doro Ln City/State/Zip: Saginaw, MI

Phone: () Fax: ()
 E-mail: Office@rightway@gmail.com Acct. Number:
 Client Name / Testing Address: 6036 Timberlane City/State (Required): Gaylord, MI

Project No.: _____ Purchase Order Number: _____

Turn Around Times: 1-Day 2-Day 3-Day Same Day (Must Call Ahead) Weekend (Must Call Ahead)

If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.

No.	Client Sample ID *	Date Collected	ASBESTOS						AIR			COMMENTS			
			FLM	FLM Point Count 400	FLM Point Count 1000	FLM NV Protocol	PCM	TEM Chatfield (Bulk)	TEMAHERA (Air)	Time On	Time Off		Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)
1	B-1	2/13/13													linoleum
2	B-2														01
3	B-3	1													11
4															
5															
6															
7															
8															
9															
10															

Released by: Scott E. Rungvik Signature: [Signature] Date/Time: 7/15/13
 Received by: M. Bressano Signature: [Signature] Date/Time: 7/16/13

LAB NOTE: SAMPLE IDENTIFICATION TAKEN FROM SAMPLE. USE CONTAINERS. MS
 07-16-13

Otsego County
Attention Mr. Burt
225 W Main St #203
Gaylord, MI 49735
July 19th, 2013

Subject: 5730 Old Stump Rd Gaylord, MI 49735

Mr. Burt,

You retained us to perform an Asbestos Survey at 5730 Old Stump Rd Gaylord, MI 49735. The purpose of this survey is to identify building material that contain asbestos and as such will require special handling procedures and or removal activity before any general demolition may take place. This survey was conducted by Scott Krugielka A27600 on July 13th, 2013.

Site

This is a 720 square foot mobile home, built prior to 1980. The heating system was forced air, it has been removed the pipes are bare. There is fiberglass insulation with aluminum siding over a wood framed structure. Rightway uses trained and licensed inspectors to attempt to locate and identify building materials that contain asbestos. It should be noted that there is the possibility that some potential asbestos containing materials (ACM) that were not found. This would be due to the fact they were inaccessible to our inspector due to an area or section being unsafe to enter. They might not have been visible or for various reasons not sampled.

Scope of Work

The scope of this work is to conform to the AHERA, ASHRA and NESHAP acts. These acts are designed to protect the environment, the worker and the public. They are mandated standards which must be complied with before, during and after abatement activities.

Sampled Material Inventory

On July 13th 2013 our inspector took 1 sample for laboratory analysis of the following items, items in bold tested positive for Asbestos.

01 12 X 12 Tile Kitchen

Laboratory Analysis Procedures

The collected samples were submitted to EHS Laboratories, Environmental Hazards Service LLC in Richmond, Virginia. EHS Laboratories, Environmental Hazards Service LLC is an accredited lab; they are accredited by the American Hygiene Association and are participants in the National Voluntary Accreditation Program. As is protocol, Rightway followed chain of custody procedures to ensure proper handling and delivery of the samples to Apex Research. After Arrival at EHS Laboratories, Environmental Hazards Service LLC the samples were analyzed using Polarized Light Microscopy with dispersion staining in accordance to the United States Environmental Protection Agency guidance document EPA/600/R-93/116 dated July 1993 "Determination of Asbestos in Bulk Building Materials."

United States Environmental Protection Agency and The National Emission Standards for Hazardous Air Pollutants defines ACM as those materials that contain greater than 1% of asbestos. Asbestos is broken down into two categories, Friable and Non-Friable. By definition Friable ACM can be defined as those that can be crumbled or reduced to powder by hand pressure.

The Occupation Safety and Health Administration standard defines both Asbestos and Asbestos containing materials. The Occupation Safety and Health Administration define ACM as any material containing more than 1% of asbestos. In areas where when ACM or Asbestos work operations do not meet the 1% standard, while considered "unclassified" are still subject to engineer and work control practices. To determine the type of fibrous components and percentage, samples are visual inspected and the ratio is determined by amount of fibrous material versus the total amount of material present.

Sampling Results and Recommendations

As previously indicated none of the items tested positive for asbestos or are assumed to be asbestos containing.

Prepared by:





Scott Krugielka
Asbestos Contract Supervisor/Asbestos Inspector
Accreditation Number: A27600
989.600.0055

Attachments:

- A: Scott Krugielka Asbestos Contractor/Supervisor license and Asbestos Inspector license
- B: Chain of Custody and Laboratory Results

Attachment A:
Scott Krugielka
Asbestos Contract Supervisor/Asbestos Inspector
Accreditation Number: 27600



Attachment B: Chain of Custody and lab results



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-07-02157

Client: Rightway Remediation Services
855 Doro Ln.
Saginaw, MI 48604

Received Date: 07/16/2013
Analyzed Date: 07/16/2013
Reported Date: 07/17/2013

Project/Test Address: 5730 Old Stump Rd; Gaylord, MI

Client Number:
23-6364

Fax Number:
989-753-4158

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-07-02157-001A	C1	Flooring	Off-White/Pale Gray Pliable; White/Light Gray Granular; Inhomogeneous	NAD	2% Cellulose 98% Non-Fibrous
13-07-02157-001B	C1	Mastic	Translucent to Pale Yellow Adhesive; Homogeneous	NAD	12% Cellulose 2% Fibrous Glass 1% Hair 85% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 23-6364

Report Number: 13-07-02157

Project/Test Address: 5730 Old Stump Rd; Gaylord, MI

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
-------------------	----------------------	------------	-----------------------	----------	-----------------

QC Sample: 13-M11996-1

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Mark Case

Reviewed By Authorized Signatory:



Howard Vamer
General Manager

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected



Asbestos Chain-of-Custody

Environmental Hazards Services, LLC
 www.ehsllab.com 7469 Whitelane Rd
 (800) 347-4010 Richmond, VA
 (804) 275-4807 (fax) 22237

Company Name: Rightway Remediation LLC Address: 855 Doro Lane City/State/Zip: Saginaw MI 48604
 Phone: 989 600 0055 Fax: 989 401 5353 E-mail: office@rightwayremed.com Asst. Number: _____
 Project Name / Testing Address: 5730 Old Stump Rd City/State (Required): Gaylord MI

Turn Around Times: 1-Day 2-Day 3-Day Same Day (Must Call Ahead) Weekend (Must Call Ahead)
 If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.

No.	Client Sample ID *	Date Collected	ASBESTOS						AIR			COMMENTS			
			FLM	FLM Point Count 400	FLM Point Count E20	FLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEMAHERA (Air)	Time On	Time Off		Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)
1	12X12 TILE C-1	7/15/13	X												12X12 TILE
2															
3															
4															
5															
6															
7															
8															
9															
10															

Released by: Scott E. Leugle Signature: _____ Date/Time: 7/15/13
 Received by: M. J. Essling Signature: _____ Date/Time: 7/16/13

13-07-02157

 Due Date:
 07/17/2013
 (Wednesday)
 AE